



2020 11th Street  
Los Osos, CA 93402  
Phone (800) 758-0978 | (805)528-6005

## TECHNICAL BULLETIN

- Lot Specific Reagent Values for Germany RiliBÄK Ranges**
- **Dimension Tacrolimus Flex Reagent Cartridge Lots GA9106 and GB9134**
  - **More Diagnostics Rap/Tac/CsA # 290 Lot # 6019**

This Technical Bulletin is for customers utilizing Germany RiliBÄK guidelines for monitoring quality control. More Diagnostics is providing quality control values specific to the Dimension Tacrolimus Flex Reagents Lot# GA9106 and GB9134, both lots were similar therefore one set of ranges were developed:

More Diagnostics Control Lot	Mean (ng/mL)	SD	Range (ng/mL)
60191	3.1	0.2	2.5-3.7
60192	8.2	0.4	7.0-9.4
60193	15.7	0.8	13.3-18.1

At More Diagnostics, we strive to provide the best quality products and services to our customers. The new value sheet is located on the website:

<https://www.morediagnostics.com/products/rap-tac-csa-controls2.php>

If you have any questions regarding this change or our products, please call More Diagnostics customer service at (800)758-0978 or (805)528-6005 or email: SALES@morediagnostics.com

More Diagnostics appreciates your business.

**John Rubino**  
Sales and Marketing Manager